



## HR292619 [CREE LED Spot Beam Light, 3360 Lumens]

### Instruction Guide

1. Disconnect wiring harness and remove light from the machine
2. Install new light onto the machine by either adding to the original bracket with the use of the provided nylon washers or you may switch to the new light bracket
3. Attach electrical connector using the included jumper
4. Adjust light to desired position and secure hardware

