

HA87602452 KIT [Hi-Lo Beam Corner Headlight Kit for Case IH Tractors, 12000 Lumens]

Instruction Guide

- 1. Disconnect wiring connector from light
- 2. Remove the four mounting bolts to remove light
- 3. Install new light into place and insert 4 mounting bolts
- 4. Once light is positioned properly, secure light by tightening all hardware
- 5. Attach electrical connectors
- 6. Repeat steps 1-6 for both lights



